

序号	报告编号	发布日期	结论	影像资料
1	GX-B1377/22-B-25157	2025. 6. 3	所检项目合格	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers standing behind a large, white, boxy industrial machine. They are in a laboratory or workshop environment with yellow curtains in the background. The technician on the left is looking at the machine, while the one on the right is looking towards the camera. A timestamp '2025.5.15' is visible in the bottom right corner of the image.
2	GX-B1377/22-B-25158	2025. 6. 3	所检项目合格	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers standing behind a large, white, boxy industrial machine. They are in a laboratory or workshop environment with yellow curtains in the background. The technician on the left is looking at the machine, while the one on the right is looking towards the camera. A timestamp '2025.5.15' is visible in the bottom right corner of the image.

3	GX-B1377/22-B-25159	2025. 6. 3	所检项目合格	
4	GX-B1378/22-B-25133	2025. 6. 3	所检项目合格	

5	GX-B1378/22-B-25115	2025. 6. 3	所检项目合格	
6	GX-B1377/22-B-25168	2025. 6. 3	所检项目合格	

7	GX-B1377/22-B-25169	2025. 6. 3	所检项目合格	
8	GX-B1378/22-B-25123	2025. 6. 3	所检项目合格	

9	GX-B1489/21-B-25043	2025. 6. 4	所检项目合格	
10	GX-B1378/22-B-25132	2025. 6. 4	所检项目合格	

11	GX-B1492/21-B-25021	2025.6.5	所检项目合格	
12	GX-B1492/21-B-25022	2025.6.5	所检项目合格	

13	GX-B1489/21-B-25064	2025. 6. 5	所检项目合格	
14	GX-B1489/21-B-25065	2025. 6. 5	所检项目合格	

15	GX-B1489/21-B-25058~B-25063	2025. 6. 5	所检项目合格	
16	GX-B1377/22-B-25173	2025. 6. 5	所检项目合格	

17	GX-B1377/22-B-25174	2025.6.5	所检项目合格	 A photograph showing two men in light blue short-sleeved shirts standing behind a large, white, boxy piece of laboratory equipment. They appear to be operating or inspecting the machine. The setting is a laboratory or office with yellow curtains in the background. A timestamp '2025.5.20' is visible in the bottom right corner of the photo.
----	---------------------	----------	--------	--