


序号	报告编号	发布日期	结论	影像资料
1	GX-B1378/22-B-25372	2025. 11. 3	所检项目合格	
2	GX-B1377/22-B-25271~B-25272	2025. 11. 3	所检项目合格	

3	GX-B1492/21-B-25053	2025. 11. 3	所检项目合格	 A photograph showing two men in a laboratory or office setting. One man, wearing a dark blue jacket, is standing next to a white machine with a circular logo on the front. The other man, wearing a grey jacket, is standing next to him. They are both looking at the machine. The background shows a window with yellow curtains and a wooden chair. A timestamp "2025.10.16" is visible in the bottom right corner of the image.
4	GX-B1489/21-B-25131	2025. 11. 3	所检项目合格	 A photograph showing two men in a laboratory or office setting. One man, wearing a grey jacket, is standing next to a white machine with a circular logo on the front. The other man, wearing a dark blue jacket, is standing next to him. They are both looking at the machine. The background shows a window with yellow curtains and a wooden chair. A timestamp "2025.10.16" is visible in the bottom right corner of the image.

5	GX-B1489/21-B-25132	2025. 11. 3	所检项目合格	 A photograph showing two men in a laboratory setting. One man, wearing a dark blue jacket, is adjusting a component on a white laboratory machine. The other man, wearing a grey shirt, is standing behind the machine, looking on. The machine has a large black hose connected to it. In the background, there are orange curtains and a yellow warning sign on the wall. A timestamp '2025.10.16' is visible in the bottom right corner of the photo.
6	GX-B1489/21-B-25142~B-25143	2025. 11. 5	所检项目合格	 A photograph showing two men in a laboratory setting. One man, wearing a light grey sweater, is operating a white laboratory machine. The other man, wearing a dark blue jacket, is standing next to him, looking at the machine. The machine has a large black hose connected to it. In the background, there are orange curtains and a yellow warning sign on the wall. A timestamp '2025.11.3' is visible in the bottom right corner of the photo.

7	GX-B1492/21-B-25066~B-25067	2025. 11. 5	所检项目合格	 A photograph showing two men in a laboratory setting. They are working on a large, white, box-like piece of equipment with a glass chamber on top. One man is wearing a blue jacket and the other is wearing a grey sweater. A yellow biohazard warning sign is visible on the wall behind them. The date '2025.11.3' is printed in the bottom right corner of the photo.
---	-----------------------------	-------------	--------	---